

OHIO STATE UNIVERSITY

(OSU) 10 NW UTC-5(-4DT) N40°04.79' W83°04.39'

DETROIT

905 B S4 FUEL 100LL, JET A1+ OX 1, 2 Class IV, ARFF Index A NOTAM FILE OSU

H-106, L-29A

RWY 09R-27L: H5004X100 (ASPH-GRVD) S-45, D-60 HIRL

IAP, AD

RWY 09R: MALSR. PAPI(P4L)—GA 3.0° TCH 51'.

RWY 27L: REIL. PAPI(P4L)—GA 3.0° TCH 26'. Tree.

RWY 05-23: H3562X100 (ASPH) S-21, D-32 MIRL 0.3% up SW

RWY 05: Trees.

RWY 23: Trees.

RWY 14-32: H3049X100 (ASPH) S-32.5, D-42, 2D-61 MIRL

RWY 14: Trees.

RWY 32: Trees

RWY 09L-27R: H2994X100 (ASPH) S-25.2 MIRL 0.4% up W

RWY 09L: VASI(V2L)—GA 3.0° TCH 29'.

RWY 27R: VASI(V2L)—GA 3.0° TCH 42'. Trees.

LAND AND HOLD SHORT OPERATIONS

| LANDING | HOLD SHORT POINT | DIST AVBL |
|---------|------------------|-----------|
| RWY 05 | 09L-27R | 3350 |
| RWY 09L | 05-23 | 2550 |
| RWY 09R | 14-32 | 3300 |
| RWY 23 | 09R-27L | 2500 |
| RWY 27L | 05-23 | 3300 |

RUNWAY DECLARED DISTANCE INFORMATION

RWY 05: TORA-3555 TODA-3555 ASDA-3555 LDA-3555

RWY 09L: TORA-2994 TODA-2994 ASDA-2994 LDA-2994

RWY 09R: TORA-5004 TODA-5004 ASDA-5004 LDA-5004

RWY 23: TORA-3555 TODA-3555 ASDA-3555 LDA-3555

RWY 27L: TORA-5004 TODA-5004 ASDA-5004 LDA-5004

RWY 27R: TORA-2994 TODA-2994 ASDA-2994 LDA-2994

AIRPORT REMARKS: Attended 1130-0400Z†. Helicopter ldg/tkfs on Twy A prohibited. Helicopter ldg/tkfs from the FBO ramp prohibited. Birds and deer on and invof arpt. Closed to scheduled air carrier ops with greater than 9 passenger seats and unscheduled air carrier ops greater than 30 passenger seats. 90-day PPR, call arpt manager 614-292-5460. Noise sensitive area within 4 miles to the N and NE. Noise abatement restrictions: No touch and go ldfs or repeated tkf and ldfs 0400-1200Z† daily. All movement area N of Rwy 09R-27L are not avbl for air carrier ops with more than 30 passenger seats. Snow removal operating procedures: when twr clsd announce arrival on freq 118.8. When twr clsd HIRL ACTIVATE MALSR Rwy 09R—CTAF. HIRL Rwy 09R-27L, and either MIRL Rwy 05-23 or Rwy 14-32 may be preset med ints in favor of forecasted wind, and MIRL Rwy 09L-27R not avbl.

WEATHER DATA SOURCES: ASOS (614) 451-2465. LAWRS.**COMMUNICATIONS:** CTAF 118.8 ATIS 121.35 UNICOM 122.95

® COLUMBUS APP/DEP CON 120.2

STATE TOWER 118.8 (1200-0400Z†) GND CON 121.7 CLNC DEL 121.7

AIRSPACE: CLASS D svc 1200-0400Z† other times CLASS G.**RADIO AIDS TO NAVIGATION:** NOTAM FILE DAY.

APPLETON (H) VORTAC 116.7 APE Chan 114 N40°09.06' W82°35.30' 265° 22.7 NM to fld. 1350/6W. HIWAS.

FULER NDB (MHW/LOM) 515 OS N40°04.42' W83°11.88' 091° 5.8 NM to fld.

ILS 108.5 I-OSU Rwy 09R Class I/E. LOM FULER NDB. Unmonitored when twr clsd.

COMM/NAV/WEATHER REMARKS: Emerg frequency 121.5 not avbl at twr.

HELIPAD H1: H40X40 (ASPH)

HELIPORT REMARKS: Helipad (unlit) relocated N side of airfield, adjacent Air Guard ramp, Twy G. All app/dep routes helicopters ops are conducted in an area 130°-110° clockwise using the touchdown pad as the center of a compass rose.

